

Hydrocodeine Correction

Notification Date: 22 APR 2019

Effective Date: 22 APR 2019

Hydrocodeine Correction

The South Bend Medical Foundation has found it necessary to correct verbiage on a component of previously run drug screen reports. The component at issue is U Dihydrocodone. Please be advised that you may see historical drug screen reports in your inbox.

The verbiage on the corrected reports is as follows:

“The original test result listed a component with an incorrect chart name of U Dihydrocodone. The correct chart name is U Dihydrocodeine. The test values, reference ranges and interpretive information have not changed. “

We apologize for any inconvenience these historical reports may cause. If you have any questions, feel free to call our Client Services department at 1-800-950-7263.

[SBMF online Test Directory](#)

Questions: Please contact **CLIENT SERVICES 800-950-7263**

Technical Notices and Lab Alerts are distributed electronically.

Email addresses may be added/unsubscribed at our website: [Client Notices](#)

SOUTH BEND MEDICAL FOUNDATION

530 North Lafayette Boulevard • South Bend, Indiana 46601
(574) 234-4176 • (800) 544-0925 • www.sbmf.org
Joyce L. Simpson, M.D. • *Medical Director*